        bc760-xltODS
7362138                                    TEXTMSWD                    £  £
                    ÷e
Subject: Bearcat Mods

Netlanders:

Concerning the Uniden Bearcat 760xlt, the mod for the 950xlt does work
to restore lost freq. Disconnect pin 20 of the microprocessor from the
circuit board and connect it to pin 19. I bent the pin slightly and cut
it with the scissors of a swiss army knife then soldered an 1/8 lead
cut from a cap across the pins near the top of the chip. I've yet to
find any problem with this mod. But as always do so at your own risk.
73 Mike WA2E @ K2DLJ


--------------------------------------------------------------------------------
-----------
This file was downloaded from the

HAM on Rye BBS  --  (814) 333-4111  --   2400-8-N-1

***************    Specializing in    ******************
Amateur radio, TVRO, scanning, shortwave and clandestine radio