

FAST-ATTACH RIFLE SILENCER QUICK START GUIDE

END CAP STRIKES

3 MAIN CAUSES

1. FAILURE TO USE ROCKSETT ADHESIVE WHEN INSTALLING MUZZLE DEVICE (FLASH HIDER, MUZZLE BRAKE) TO HOST RIFLE MUZZLE.
2. FAILURE TO PROPERLY CLEAN/DEGREASE MUZZLE THREADS AND MUZZLE DEVICE BEFORE INSTALLING MUZZLE DEVICE WITH ROCKSETT.
3. FAILURE TO PROPERLY INSTALL SILENCER ON MUZZLE DEVICE PRIOR TO DISCHARGING RIFLE.

PREVENTING END CAP STRIKES

1. Figure 1 identifies the plastic packet of Rocksett sealant included with all AAC silencer-mounting muzzle devices. Install all AAC silencer-mounting muzzle devices using the supplied Rocksett and recommended torque. See the Muzzle Device Installation card or the AAC website for full details and instructions.



Figure 1

2. Figure 2 below identifies in RED the threads on the host rifle muzzle and the threads in the rear of the muzzle device. These threads must be cleaned and degreased with a solvent such as acetone, paint thinner, or lacquer thinner prior to applying the recommended amount of Rocksett adhesive. Remove any dirt or old adhesive residue from the muzzle threads using solvent and a brush. See the Muzzle Device Installation card for full details and instructions.



Figure 2

Flip card over to continue.

3. Figures 3 and 4 detail how to fully engage the silencer with the muzzle device prior to discharging the rifle. AAC Ratchet Mount™ silencers use a section of ACME thread to couple the silencer to the muzzle device. One and a half to two full revolutions of the silencer are necessary to fully engage the threads in the rear of the silencer with the threads on the exterior of the muzzle device. As the silencer is threaded onto the muzzle device, the spring biased ratchet latch on the silencer will engage the teeth on the muzzle device. The engagement of the ratchet latch and teeth can be heard and felt. Thread the silencer fully onto the muzzle device until it stops. See the AAC Centerfire Rifle Silencer Manual for complete details on the proper installation of an AAC Fast-Attach rifle silencer.



Figure 3



Figure 4



ADVANCED ARMAMENT CORP.
770-925-9988 (Voice) 770-925-9989 (Fax)
www.advanced-armament.com

REV 0.0 NOV2013

We strongly recommend having all AAC muzzle devices installed by a competent gunsmith. AAC™ is not liable for damage(s) to the host weapon, silencer, and user attributed to improper installation.